




VOLKSWAGEN OF AMERICA, INC.

2000 E. 10th Avenue

100-0000

100-0000



Sinclair and Jane Rogers
333 North Cedar Brook Box 112
Monett, Missouri 65708
Tele: 235-6180

SOLD TO
ADDRESS

MAKE	MODEL	NEW OR USED	CHASSIS NO.	ENGINE NO.
73 Porsche	911T	New	9113100912	6121383

SALESMAN	Perrin	KEY NOS.	NC327 HC327
----------	--------	-------------	-------------

INSURANCE COVERAGE INCLUDES	
FIRE & THEFT <input type="checkbox"/>	<input type="checkbox"/> PUBLIC LIABILITY - AMT.
COLLISION - AMT. DEDUCTIBLE <input type="checkbox"/>	<input type="checkbox"/> PROPERTY DAMAGE - AMT.

OPTIONAL EQUIPMENT AND ACCESSORIES	GROUP	DESCRIPTION	PRICE
		K. Green	
		AM/FM 8 track stereo	
		Porsche Stripe	
		Mileage: 283	
		Lien Holder: none	

USED CAR TRADED				
YEAR	MAKE	MODEL	CHASSIS NO.	ENGINE NO.

BODY COLOR

DATE	INVOICE NO.	STOCK NO.
6/12/73	01472	131
DESCRIPTION OF TRANSACTION		AMOUNT
NEW VW TYPE 113/7		
NEW KARM (14 & 15)		
NEW VW TYPE 3 F.B.		
NEW VW TYPE 3 S.B.		
NEW VW TYPE 2 S.W.		
NEW VW TYPE 2 TRK.		
NEW VW TYPE 111		
NEW VW TYPE 4		
VOLKSWAGEN DEMO.		
NEW UNITS-OTHER MAKES		8300.00
DEALER INSTALLED ACCESS.		150.00
OVERALLOWANCE/DISCOUNT		
USED VW - RETAIL		
USED OTHER RETAIL		
USED WHOLESALE		
INVENTORY-NEW VEHICLE		
SALES TRANSACTION NUMBER		570
LICENSE FEES		
SALES TAX		
TOTAL CASH PRICE		8450.00
FINANCING		
INSURANCE		
TOTAL TIME PRICE		
DEPOSIT		
CASH ON DELIVERY		8450.00
VEHICLE ACCOUNTS RECEIVABLE		
USED CAR ALLOWANCE		
PAYMENTS		
MONTHS DOLLARS		
@ PER MONTH		
TOTAL		

Thank you
for this opportunity
to be of service

Owner's Name SINCLAIR ROGERS
 Street Address 333 No. Cedar brook.
 City Monett, Mo. 65708
 Car 01 Pickup/Panel 02 Straight Trk 03 Sch Bus 04
 Trk-Tractor 05 Trailer 06 Bus 07 Motorcycle 08
1973 Porsche Mileage 80392
 (Year) (Make)
 V.I.N. 9113100912

REJECTION: Each item of equipment or its component checked on the code line to the right of the listed item or component does not comply with the inspection standards. Repairs may be made by yourself or at any place of your choice. No additional inspection fee will be charged for a reinspection if the vehicle is repaired and returned to this station within ten days.

Date I/M Signature & No.

The following is an estimated cost to repair rejected items or components. List items or components as a three digit code. Example, the code for a rejected tail light would be A04.

Item/Comp. Codes	Parts	Labor	Total Cost

As the vehicle owner, I understand that I am not required to have needed repairs made by the official inspection station, however, I authorize the station to repair the unsafe items or components which were discovered during the inspection.

Owner's Signature

APPROVAL: I certify that I have properly inspected each item of equipment required to be inspected and that all items and components are in proper mechanical condition to be operated with safety upon the public highways.

Sticker or decal No. 1508089 has been issued this date 6-11-73 and the white copy of MVI-2 given to the owner as a certificate of approval.

I/M Signature & No. Dick Smiller 7145
 Station Name McCallister VW
 Station Address 3600 Glenstone Station No. 039017

SAFETY INSPECTION CHECK LIST

(For specific details consult manual)

APP.

- ☒ **A LIGHTING EQUIPMENT, SIGNALING DEVICES**
 High beam 01 Low beam 02 Indicator 03
 Tail Lights 04 Reflectors 05 Stop Lights 06
 Turn Signals 07 Lenses 08 Signal Indicator 09
- ☒ **B HORN**
 Proper function and connections 01
- ☒ **C STEERING MECHANISMS**
 Wheel alignment 01 Rear tracking 02
 Steering wheel play 03 Binding 04
 Wheel bearing adjustment: LF 05 RF 06
 Tie rods 07 Idler arm 08
 Stabilizer link 09 Pitman arm 10
 Ball joints: RF LF UP LO 11
 Play in front wheels: LF RF 12
 Broken springs, torsion bars and shackles 13
 Shock absorbers: LF RF LR RR 14
 Power steering belt 15
- ☒ **D BRAKES** (air only)
 Pedal reserve 01 Emergency/Park 02
 Stopping distance and equalization 03
 Leaks in system (including wheel cylinder) 04
 Proper fluid level in master cylinder 05
 Drum/disc 06 linings/pads 07 Linkage 08
 Mark the brake inspected LF RF LR RR
- ☒ **E TIRES AND WHEELS**
 Tread wear, exposed cord, knots, non highway use LF LR RF RR 01
 Mis-matched duals or tire-types on same axle 02
 Damaged wheels, studs, missing lugs 03
- ☒ **F WINDSHIELD WIPERS**
 Operation, condition of arm/blade 01
- ☒ **G MUFFLER, EXHAUST, AND TAILPIPE**
 Leakage and secureness of mounting 01
- ☒ **H WINDSHIELD AND OTHER GLASS**
 Approved type, badly cracked or broken 01
- ☒ **I MIRROR**
 View to rear and proper mounting 01
- ☒ **J FRONT SEAT BELTS** (1965 or later passenger cars only)
 Required installation 01
- ☒ **K AIR POLLUTION CONTROL DEVICES**
 (1968 and later)
 Required installation and proper operation 01
- ☒ **L MUD FLAPS** (Commercial vehicles only)
 Required mounting and proper width 01
- ☒ **M FUEL TANK**
 Leaks, secure mounting, filler cap 01
- ☒ **N SPECIAL SCHOOL BUS EQUIPMENT**
 Flashing red lights 01 Clearance lights 02
 Stop arm Lettering Bumper 03
 Emergency door/buzzer Service door 04
 Seats Step treads/aisle mats 05
 Extinguisher First aid kit Flares 06

B- 3065412



State of Missouri

Certificate of Title

718 C302 085

ORIGINAL

OWNER

ROGERS SINCLAIR &/OR JANE
BOX 112
MONETT
MO 65708

TITLE NUMBER K340227 DATE ISSUED 06/29/73

TAX 253.50 MANUFACTURER'S IDENT. NO. 911310C912

MAKE BODY STYLE YR. CYL. H. P.
PORS CCUPE 73 04 26

MAIL TO

ROGERS SINCLAIR &/OR
BOX 112
MONETT
MO 65708

FIRST - LIEN

VEHICLE SUBJECT TO LIEN
DATE CREATED

SECOND - LIEN

THIS WILL CERTIFY THAT REASONABLE DILIGENCE HAS BEEN USED IN ASCERTAINING WHETHER OR NOT THE STATEMENTS IN THIS APPLICATION FOR THE CERTIFICATE OF TITLE ARE TRUE. THEREFORE, I CERTIFY THAT THE APPLICANT HEREIN NAMED HAS BEEN DULY REGISTERED AS THE OWNER, SUBJECT ONLY TO THE LIEN RECORDED AT THE DATE OF ISSUANCE OF THIS CERTIFICATE.

Jack Spaulding
DIRECTOR OF REVENUE

(A) OFFICE USE ONLY

81 JUN 12 1973 PAID

K3A-914

266.00

TYPE OF TITLE		ORIG <input checked="" type="checkbox"/>	DUPL <input type="checkbox"/>	CORR. <input type="checkbox"/>	NON-NEG <input type="checkbox"/>	REPO <input type="checkbox"/>	OFFICE USE ONLY	
FULL NAME(B)		LAST		FIRST		MIDDLE		TYPE OF TENANCY
TYPE ONLY		ROGERS, Sinclair and/or Jane						
ADDRESS(C)		333 North Cedarbrook		Box 112		Barry		ENTIRETIES
CITY(D)		Monett, Missouri		STATE		ZIP CODE		JOINT
YEAR(H)		73		MAKE(E)		PORS		COMMON
DO NOT USE(F)				VEHICLE IDENTIFICATION NUMBER(G)		9113100912		PARTNERSHIP
SERIES OR MODEL (I)	BODY STYLE (I)		NEW(J)	USED(J)	CYL(K)	BORE	HP(L)	VEHICLE CATEGORY(M)
911T	Coupe		X		4		26	Auto
PREVIOUS TITLE NO.	STATE	ZONE	GR. WT. OR SEAT CAP.(N)	CLASS(O)	AXLES(P)	GASOLINE (Q)	DIESEL(Q)	L.P. GAS (Q)
MSO								
VEHICLE SUBJECT TO LIEN		DATE		PRICE		s 8450.00		
1ST LIEN(U) <input type="checkbox"/> MAIL TO(V) <input type="checkbox"/>				TRADE IN		s n.a.		
STREET OR BOX NO.				NET PRICE		s 8450.00		
CITY & STATE				STATE TAX (S)		253.50		
2ND LIEN(W) <input type="checkbox"/> MAIL TO(X) <input type="checkbox"/>				CITY TAX (Z)				
STREET OR BOX NO.				PURCHASE DATE (T)		6/12/73		
CITY & STATE								
I HEREBY CERTIFY THAT THE FACTS HEREIN ARE TRUE AND I AM NOT UNDER SUSPENSION OR REVOKED.								
SIGNATURE OF OWNER X <i>[Signature]</i>								
I CERTIFY THAT THE FACTS HEREIN ARE TRUE TO THE BEST OF MY KNOWLEDGE								
NAME OF FIRM		McCallister Volkswagen, Inc.						
CITY & STATE		Springfield, Missouri						
DEALER NO. (Y)		Clerk						
SIGNED BY X								
NOTARY SIGNATURE AND SEAL		DATE NOTARIZED		MY COMMISSION EXPIRES				
<i>[Signature]</i>		6/12/73		11/22/76				
ENTER FEES	TITLE(T)	TRANSFER(T)	RENEWAL(T)	LICENSE(T)				
FOR ITEMS	1.00			11.50				
REQUIRED	TITLE PTY.	E.H.P.	REN. PTY.	STATE TAX	TOTAL STATE FEES			
				253.50	266.00			
CITY SALES TAX DATA	NAME OF CITY (Z)				CITY TAX (Z)			
LICENSE - TRANSFER INFORMATION	LICENSE NO.	YEAR	MAKE	H.P.	VEHICLE IDENTIFICATION NUMBER			
REMARKS					IMPORTANT			
					PERSONAL PROPERTY TAX AND INSPECTION CERTIFICATE VERIFIED BY			
SEE INSTRUCTIONS BACK SIDE					X <i>mlf</i>			



McCallister Volkswagen, Inc.
PORSCHE | AUDI

3600 S. Glenstone
Phone 883-8800
Springfield, Missouri 65804

PORSCHE

No. 2771



AUTHORIZED DEALER



RECEIVED OF

Eight Thousand four hundred and 8450.00
DOLLARS
and fifty dollars and 00/100

DETAIL	ACCOUNT	NOTE	HOW PAID
Amount Due			Cash
Amount Paid			Check <i>i</i>
			Draft
Balance Due			Money Order

BY

#570

THANK YOU

MILEAGE VERIFICATION

McCallister Volkswagen, Inc.

I, _____, state that the odometer mileage indicated on the vehicle described below is 283 miles

(Check the following statement, if applicable)

☐ I further state that the actual mileage differs from the odometer reading for reasons other than odometer calibration error and that the actual mileage is unknown.

Make	Body Style	Year	Model
Pors	coupe	1973	911T
Vehicle Identification Number 9113100912		Last Plate Number	

Transferor's Address Springfield, Missouri

Transferor's Signature *Susan H. [unclear]*

Date of this Statement 6/12/73

\$ 8,517.00



DEALER INSTALLED ACCESSORIES

DEALER PREPARATION	\$ 75.00
STEREO AM-FM RADIO AND 8-	\$
TRACKTAPE PLAYER	\$ 200.00
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
TOTAL DELIVERED PRICE	\$ 8,792.00

McCALLISTER



PORSCHE | AUDI

3600 SOUTH GLENSTONE AVE.

SPRINGFIELD, MISSOURI 65804

417-883-8800

YOUR NEW CAR AND ITS' POLLUTION CONTROLS

Each year since 1969 all new cars have had more pollution devices added to them and this trend will get more complex until 1975. These are built right into the car and may not be disconnected without being subject to a Federal fine and in many cases cannot be disconnected at all because of their integral construction into the car.

Among the pollution controls are filters for the crankcase, carburetor, and fuel tank. There are control devices built into the carburetor and distributor. The amount of carburetor and ignition timing adjustment range has been reduced nearly 60 percent since 1969. In other words . . . all new cars now run lean on gasoline and retarded on ignition timing and we cannot materially change this.

It can and does affect your car performance and all makes of cars are affected. You will experience practically no problems at highway speeds. At slower speeds you may notice a "hesitation" or a "surge". It is not an engine "miss" as many people think.

To eliminate this may require several service calls since it is ultra fine tuning that will help cure it and it may reappear unexpectedly. It appears that more mileage put on a car seems to eliminate it also. We ask your patience to help solve this if it occurs. Please be assured that we will get it corrected, but it can be difficult in certain cases. Our automobiles are not the only ones affected and if you like we can document this situation with articles and publications. We just feel that our valued customers should know the facts of pollution controls and that we do not knowingly make excuses when others might, and that we will always be "at your service".

McCALLISTER VOLKSWAGEN, INC.

A handwritten signature in dark ink, appearing to read 'Ray Cowperthwaite', enclosed within a large, loopy oval.

Ray Cowperthwaite
General Manager

McCALLISTER VOLKSWAGEN INC.